



NO.	CURVE DATA	LONG CHORD
1	114° 02' 57"	11498.20'
2	01° 52' 49"	15283.50'
3	01° 52' 49"	15283.50'

Basis of Bearings
 The bearings are based on the south line of Section 34 bearing S 89° 54' 11" E, as taken from the State Plane Coordinate System, NAD83 2011 Adjustment, Goid 620099107, Ohio South Zone, O.D.O.T. ORTN/COBS Network.

Occupation Statement
 Monumented property lines generally fit occupation where occupation exists.

Monumentation Statement
 Monumentation is correct as shown and in good condition unless shown otherwise.

- Legend**
- Iron pin found
 - ▲ 1/2" iron pipe found
 - 3/4" iron pipe found
 - 1/2" iron pipe found
 - Iron nail set
 - Iron pin found

- References**
- Vol. 18, Pg. 153
 - Vol. 18, Pg. 152
 - Vol. 18, Pg. 156
 - Vol. 21, Pg. 70
 - Vol. 22, Pg. 159
 - Vol. 24, Pg. 186
 - Vol. 30, Pg. 100
 - Vol. 32, Pg. 139
 - Vol. 35, Pg. 48
 - Vol. 38, Pg. 181
 - Vol. 61, Pg. 174
 - Vol. 61, Pg. 41
- Record of Land Surveys

Split of 74,968 acres for D.A. Bowman Construction.

Surveyor's Certification
 I, the undersigned, being a duly licensed Surveyor of the State of Ohio, do hereby certify that this boundary survey or plat of survey was prepared in accordance with the Ohio Administrative Code Chapter 4733-57, Standards for Boundary Surveys.

Michael W. Cozatt, P.S. #6001 Date _____

Cozatt Engineering Company
 Land Surveyor
 1100 Wayne Street, Ste. 1140 Troy Ohio
 Job No. 2002212 Ph. (937) 339-2921

