

# STATE OF TEXAS WELL REPORT for Tracking #57675

Owner: <b>French John Creek Ranch</b> Address: <b>204 Windcrest Fredericksburg, TX 78624</b> Well Location: <b>1miSfrom Hwy29 on1431;1000' W in pasture (next to Liquor Store Fence), Lot #15 TX</b> Well County: <b>Llano</b>	Owner Well #: <b>No Data</b> Grid #: <b>57-21-1</b> Latitude: <b>30° 43' 02" N</b> Longitude: <b>098° 28' 15" W</b> Elevation: <b>No Data</b>
---	---

Type of Work: <b>New Well</b>	Proposed Use: <b>Domestic</b>
-------------------------------	-------------------------------

Drilling Start Date: **4/26/2005**      Drilling End Date: **4/26/2005**

Borehole:	Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)
	<b>9</b>	<b>0</b>	<b>81</b>

Drilling Method: **Air Hammer**

Borehole Completion: **Filter Packed**

Filter Pack Intervals:	Top Depth (ft.)	Bottom Depth (ft.)	Filter Material	Size
	<b>25</b>	<b>81</b>	<b>Gravel</b>	<b>4A</b>

Annular Seal Data:	Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
	<b>0</b>	<b>8</b>	<b>1 Cement</b>
	<b>8</b>	<b>25</b>	<b>5 Bentonite</b>

Seal Method: **Grout**

Sealed By: **Driller**

Distance to Property Line (ft.): **55**

Distance to Septic Field or other concentrated contamination (ft.): **n/a**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **measure**

Surface Completion: **Surface Sleeve Installed**

Water Level: **20 ft. below land surface on 2005-04-26**      Measurement Method: **Unknown**

Packers: **No Data**

Type of Pump: **Submersible**      Pump Depth (ft.): **60**

Well Tests: **Jetted**      Yield: **60 GPM**

Water Quality:	Strata Depth (ft.)	Water Type
	<b>30 - 81</b>	<b>good (580 ppmTDS)</b>

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Virdell Drilling Inc.**  
**111 E. Grayson St.**  
**Llano, TX 78643**

Driller Name: **Lynn Hoy** License Number: **4071**

Comments: **Amended 6/21/06 Ref.#3615**

**Report Amended on by Request #3615**

Lithology:  
 DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing:  
 BLANK PIPE & WELL SCREEN DATA

Top (ft.)	Bottom (ft.)	Description
<b>0</b>	<b>2</b>	<b>Topsoil</b>
<b>2</b>	<b>8</b>	<b>Granite Gravel &amp; Clay</b>
<b>8</b>	<b>81</b>	<b>Granite Gravel</b>

Dia. (in.)	New/Used	Type	Setting From/To (ft.)
<b>6"</b>	<b>N</b>	<b>PVC +2 - 76 sch 40</b>	
<b>6"</b>	<b>N</b>	<b>PVC, Custom Slott 76 - 81 sch 40</b>	

**IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY**

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

**Texas Department of Licensing and Regulation**  
**P.O. Box 12157**  
**Austin, TX 78711**  
**(512) 334-5540**